

Notice to Mariners No 02/26

ARDERSIER PORT – Temporarily inoperative AtoN

Mariners are advised that the navigation buoy AP01-D (57°36.79'N 003°59.38'W) is temporarily inoperative. Both light and AIS function has been affected.

The buoy manufacturer has been informed and are working to correct as soon as possible.

Local Notice to Mariners are available on the Haventus website;
www.haventus.com

Capt. Donald MacKenzie
Harbour Master